

Annexure D

BUILDING SAFETY CERTIFICATE

No. 34

Dated: 25.01.2025

It is certified that the existing building **SHRI GURU TEG BAHADUR PUBLIC SCHOOL** (name of the building or premises) at **VILL. MAHENGAPUR TEHSIL PALIA KALAN Lakhimpur-Kheri (UP)** (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ground + 01	NA	NA	NA	NA	NA

The building is owned/occupied by **SHRI GURU TEG BAHADUR PUBLIC SCHOOL** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Rural Engineering Department** (Name of Department/ Govt.) on **25.01.2025** (date of inspection) in the presence of **Mr. Tirath Singh Sandhu Vill. Mahengapur Tehsil Palia Kalan Lakhimpur- Kheri (UP)** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **25.01.2025** for a period of **Five Years** in accordance with rule and subject to compliance of the specific conditions as appended.

- 5- If intensity of earthquake in this region occurs more than 06.00 on reactor scale this certificate become invalid, inspection of building should be done again.
- 6- If No's of floor is increased then this certificate become invalid.

Issued on 25.01.2025 at Lakhimpur by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : _____

R. Srivastava
रवि शंकर श्रीवास्तव
सहायक अभियन्ता
ग्रामीण अभियन्त्रण विभाग
प्रखण्ड-लखीमपुर-खीरी

Name : _____

Designation : _____

Name & Address of Department/ Office: _____